


**PEUGEOT 5008: 2BHF711**

Vinnnumber:	<b>VF3MCYHZMMS228055</b>	Versionname:	<b>5008 1.5 BlueHDi S/S Allure Pack 96kW/130pk 5D/P Man-6</b>
First Registrationdate:	<b>25/11/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>86353</b>	Power Kw:	
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Front</b>	Parking lot:	<b>a210</b>
Fueltype:	<b>Diesel</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Bodywork:	<b>Clean</b>		
Interior:	<b>Clean</b>		

**Options**

Number of keys total:	<b>2</b>	Radio:	
Number keys remote:	<b>2</b>	Front parking sensors:	
Windows electric F:		Rear parking sensors:	
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

**Limited Technical Inspection**

Idle position:	<b>OK</b>	Sound engine:	<b>OK</b>
Engine startingtime:	<b>OK</b>	Clutch test:	<b>OK</b>
Exhaust gass:	<b>OK</b>	Transmission:	<b>OK</b>

**Tyres**

	<b>225/55/18/102 V</b>			
Winter tyres:	Fr.L.	<b>Vredestein: 3 mm</b>	Fr.R.	<b>Vredestein: 3 mm</b>
	Re.L.	<b>Vredestein: 3 mm</b>	Re.R.	<b>Vredestein: 3 mm</b>
Tyre profile depth FL:				<b>3.0</b>
Tyre profile depth FR:				<b>3.0</b>
Tyre profile depth RL:				<b>3.0</b>
Tyre profile depth RR:				<b>3.0</b>
Tyre size FL:				<b>225/55 R 18 102 V</b>
Tyre size FR:				<b>225/55 R 18 102 V</b>
Tyre size RL:				<b>225/55 R 18 102 V</b>
Tyre size RR:				<b>225/55 R 18 102 V</b>
Tyre type FL:				<b>Winter</b>
Tyre type FR:				<b>Winter</b>
Tyre type RL:				<b>Winter</b>
Tyre type RR:				<b>Winter</b>
Tyre make FL:				<b>2480</b>
Tyre make FR:				<b>2480</b>
Tyre make RL:				<b>2480</b>
Tyre make RR:				<b>2480</b>


**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Instrument panel, complete, Repaired, Acceptable




Seat cover FL, Hole, Smart repair



Seat cover FR, Stain, Cleaning



Centre console, Scratch(es), Smart repair



Bumper moulding F, Broken, Replace



Bumper F, Scratch(es), Acceptable



Bonnet, Dent(s), Acceptable



Windscreen, Stone chip(s), Windscreen repair




Roof pillar L, Dent(s), Acceptable



Door FL, Scratch(es), Polish



Wing FL, Scratch(es), Polish




Step L, Dent(s) and scratch(es), Spot repair



Door RL, Dent(s), Acceptable




Wing RL, Scratch(es), Acceptable




Internal boot lining L, Scratch(es), Smart repair



Internal boot lining R, Scratch(es), Smart repair



Boot lid covering R, Scratch(es), Smart repair



Tailgate / Boot, Scratch(es), Acceptable




Rear light L tailgate, Scratch(es), Polish




Rear light L, Scratch(es), Polish



Rear light R tailgate, Crack, Replace




Bumper trim R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)





Door FR, Scratch(es), Polish



Door RR, Scratch(es), Polish



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Bodywork, No damage, Acceptable



Roof, Scratch(es), Repair and paint (complete)

