



HYUNDAI Nexo: CDBA341

Vinnumber:	KMHJ8816FLY008830	Versionname:	Nexo FCEV 1 (Hydrogen) 120kW/163pk 5D/P Auto-1
First Registrationdate:	31/05/2022	Fiscalpower:	
Expertise Mileage:	39655	Power Kw:	120
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	d328
Fueltype:	Gas		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Lining leather
Windows electric F		Sun Roof electric
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		Fog lights (front)
Seats F heated		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Degree of wear

245/45/19/102 V				
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				245/45 R 19 102 V
Tyre size FR				245/45 R 19 102 V
Tyre size RL				245/45 R 19 102 V
Tyre size RR				245/45 R 19 102 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				257

Tyre make FR	257
Tyre make RL	257
Tyre make RR	257

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Ignition key, Worn, Acceptable			



Floor covering FL, Dirty, Cleaning			

Backrest cover FR, Scratch(es), Acceptable			

Bumper moulding F, Scratch(es), Acceptable			

Windscreen, Stone chip(s), Acceptable			

Alloy rim RL polished, Scratch(es), Acceptable			

Step L, Dent(s) and scratch(es), Acceptable			

Door RL, Dent(s) and scratch(es), Acceptable			

Door FL, Dent(s) and scratch(es), Spot repair			



Door trim FL, Scratch(es), Acceptable



Outside rear-view mirror housing L, Broken, Replace



Outside rear-view mirror base L, Scratch(es), Smart repair



Mirror side repeater L, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable




Alloy rim FL polished, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Acceptable



Internal boot lining L, Scratch(es), Acceptable




Boot lid covering R, Scratch(es), Acceptable






Bumper moulding R, Scratch(es), Smart repair




Bumper trim R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Wing FR, Dent(s), Acceptable





Step R, Dent(s) and scratch(es), Spot repair



Door trim FR, Scratch(es), Acceptable



Door trim RR, Scratch(es), Acceptable



Door RR, Dent(s) and scratch(es), Spot repair



Wing trim RR, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable

