



PEUGEOT 2008: 2CML619			
Vinnumber:	VR3USHNSKNJ720931	Versionname:	2008 1.2 Puretech S/S Active Pack 96kW/130pk
First Registrationdate:	15/09/2022	Fiscalpower:	5D/P Man-6
Expertise Mileage:	62763	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	b317
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options	
Number of keys total	2
Number keys remote	1
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Navigation with screen	
Airco electronic	
Rims alloy	

Limited Technical Inspection			
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres			
215/65/16/98 H			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R. Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R. Continental: 4 mm
Tyre profile depth FL			4.0
Tyre profile depth FR			4.0
Tyre profile depth RL			4.0
Tyre profile depth RR			4.0
Tyre size FL			215/65 R 16 98 H
Tyre size FR			215/65 R 16 98 H
Tyre size RL			215/65 R 16 98 H
Tyre size RR			215/65 R 16 98 H
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			256
Tyre make RL			256
Tyre make RR			256

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Instrument panel, complete, Repaired, Acceptable




Bumper F, Scratch(es), Spot repair




Bumper spoiler F, Scratch(es), Smart repair




Bonnet, Chemical polution, Polish




Windscreen, Repaired, Acceptable




Outside rear-view mirror housing L, Scratch(es), Acceptable




Roof pillar L, Dent(s), Acceptable




Door FL, Scratch(es), Acceptable



Wing RL, Scratch(es), Polish



Door RL, Scratch(es), Polish



Tailgate / Boot, Scratch(es), Acceptable



Boot moulding, Scratch(es), Polish



Bumper R, Scratch(es), Acceptable




Alloy rim FR, Scratch(es), Acceptable




Outside rear-view mirror housing R, Scratch(es), Acceptable



Door FR, Dent(s) and scratch(es), Spot repair



Door RR, Dent(s) and scratch(es), Spot repair



Alloy rim RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Hail damage, Paintless dent repair (hail)

