


SKODA Octavia Combi: 2BLU276

Vinnnumber:	TMBJJ7NX3NY006481	Versionname:	Octavia Combi 2.0 CRTDI Clever+ 110kW/150pk
First Registrationdate:	6/01/2022	Fiscalpower:	5D/P Man-6
Expertise Mileage:	65023	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	pp10
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	3	Radio	
Number keys remote	3	Sun Roof electric	
GPS storage		Front parking sensors	
GPS storage	HD	Rear parking sensors	
Windows electric F		Fog lights (front)	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Transmission	OK
Exhaust gass	OK		

Tyres

205/55/17/91 H				
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				6.0
Tyre profile depth RL				5.0
Tyre profile depth RR				6.0
Tyre size FL				205/55 R 17 91 H
Tyre size FR				205/55 R 17 91 H
Tyre size RL				205/55 R 17 91 H
Tyre size RR				205/55 R 17 91 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Number of charging cables (normal)
Number of charging cables (rapid charge)

0
0

Instrument panel, complete, Repaired, Acceptable



Ignition key, Not functioning (well), Acceptable




Bumper F, Scratch(es), Acceptable



Bonnet, Dent(s), Paintless dent repair



Wing FL, Scratch(es), Polish




Step L, Dent(s), Acceptable



Door RL, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable







Tailgate / Boot, Scratch(es), Spot repair



Alloy rim FR, Scratch(es), Repair and paint (complete)



Door RR, Repaired, Acceptable



Wing RR, Repaired, Acceptable



Bodywork, Inspection +, Photo complémentaire



Bodywork, No damage, Acceptable

