



HYUNDAI Kona: 1YPY092

Vinnnumber:	KMHK581GFLU086972	Versionname:	Kona Electric Sky 64kWh 150kW/204pk 5D/P Auto-1
First Registrationdate:	30/10/2020	Fiscalpower:	
Expertise Mileage:	56573	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	a105
Fueltype:	Electric		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio	
Number keys remote:	2	Lining leather	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Fog lights (front)	
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK


Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 55 / 17 / 94 / V / Aluminium	4,0 mm	Nexen	Summer
	Right	215 / 55 / 17 / 94 / V / Aluminium	4,0 mm	Nexen	Summer
Rear	Left	215 / 55 / 17 / 94 / V / Aluminium	5,0 mm	Nexen	Summer
	Right	215 / 55 / 17 / 94 / V / Aluminium	5,0 mm	Nexen	Summer

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	1		

Instrument panel, complete, Repaired, Acceptable



Bumper F, Crack, Replace and paint



Fog lamp R, Scratch(es), Replace




Bumper moulding F, Scratch(es), Replace




Bumper spoiler F, Scratch(es), Replace



Bumper grille, Crack, Replace



Bonnet, Chemical pollution, Polish



Bumper moulding F, Scratch(es), Replace



Alloy rim FL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)




Outside rear-view mirror base L, Scratch(es), Smart repair



Door FL, Scratch(es), Repair and paint (complete)




Door RL, Scratch(es), Repair and paint (complete)



Outer door handle FL, Scratch(es), Repair and paint (complete)




Wing trim RL, Scratch(es), Acceptable



Alloy rim RL, Scratch(es), Polish



Rear spoiler, Chemical polution, Polish




Alloy rim FR, Scratch(es), Repair and paint (complete)




Door FR, Dent(s) and scratch(es), Repair and paint (complete)





Door RR, Dent(s), Forfeit



Wing RR, Scratch(es), Spot repair



Alloy rim RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Dent(s), Acceptable

