




HYUNDAI Nexo: CDBA332				
Vinnnumber:	KMHJ8816FLU008829	Versionname:	Nexo FCEV 1 (Hydrogen) 120kW/163pk 5D/P Auto-1	
First Registrationdate:	17/02/2022	Fiscalpower:		
Expertise Mileage:	26198	Power Kw:		
Bodytype:		Body colour	Grey	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:	Front	Parking lot	d340	
Fueltype:	Electric			
Number of doors	5			
Number of seats	5			
Number head rests	5			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Bodywork	Clean			
Interior	Clean			
Options				
Number of keys total	2	Radio		
Number keys remote	2	Lining leather		
Windows electric F		Sun Roof electric		
Windows electric R		Front parking sensors		
Cruise Control		Rear parking sensors		
Steering wheel multifunctional				
Seats F heated				
Navigation with screen				
Airco electronic				
Rims alloy				
Limited Technical Inspection				
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Transmission	OK	
Tyres				
Winter tyres:	245/45/19/102 V			
	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				245/45 R 19 102 V
Tyre size FR				245/45 R 19 102 V
Tyre size RL				245/45 R 19 102 V
Tyre size RR				245/45 R 19 102 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				257
Tyre make FR				257
Tyre make RL				257
Tyre make RR				257
Assistance equipment				
Repair kit	Yes	Compressor		Yes
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			

Door panel RR, Scratch(es), Acceptable



Bumper spoiler F, Scratch(es), Smart repair



Fog lamp L, Scratch(es), Polish



Alloy rim FL polished, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Bumper moulding R, Scratch(es), Acceptable



Rear light L tailgate, Crack, Replace



Alloy rim FR polished, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Acceptable



Door FR, Dent(s) and scratch(es), Spot repair



Central pillar R, Dent(s) and scratch(es), Spot repair



Door RR, Dent(s) and scratch(es), Spot repair



Alloy rim RR polished, Scratch(es), Acceptable



Wing RR, Scratch(es), Polish



Bodywork, No damage, Acceptable

