


**PEUGEOT 508 SW: 2ACT548**

Vinnumber:	<b>VR3FCYHZTY051610</b>	Versionname:	<b>508 SW 1.5 BlueHDi 130 S/S EAT8 Allure Pack</b>
First Registrationdate:	<b>22/02/2021</b>	Fiscalpower:	<b>96kW/130pk 5D/P Auto-8</b>
Expertise Mileage:	<b>40313</b>	Power Kw:	
Bodytype:		Body colour:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Front</b>	Parking lot:	<b>pp64</b>
Fueltype:	<b>Diesel</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Bodywork:	<b>Clean</b>		
Interior:	<b>Clean</b>		

**Options**

Number of keys total:	<b>2</b>	Radio
Number keys remote:	<b>2</b>	Front parking sensors
Windows electric F:		Rear parking sensors
Windows electric R:		
Cruise Control:		
Steering wheel multifunctional:		
Seats F heated:		
Navigation with screen:		
Airco electronic:		
Rims alloy:		

**Limited Technical Inspection**

Idle position:	<b>OK</b>	Sound engine:	<b>OK</b>
Engine startingtime:	<b>OK</b>	Clutch test:	<b>OK</b>
Exhaust gass:	<b>OK</b>	Transmission:	<b>OK</b>

**Tyres**

<b>215/55/17/98 V</b>				
Winter tyres:	Fr.L.	<b>Firestone: 4 mm</b>	Fr.R.	<b>Firestone: 4 mm</b>
	Re.L.	<b>Firestone: 4 mm</b>	Re.R.	<b>Firestone: 4 mm</b>
Tyre profile depth FL:				<b>4.0</b>
Tyre profile depth FR:				<b>4.0</b>
Tyre profile depth RL:				<b>4.0</b>
Tyre profile depth RR:				<b>4.0</b>
Tyre size FL:				<b>215/55 R 17 98 V</b>
Tyre size FR:				<b>215/55 R 17 98 V</b>
Tyre size RL:				<b>215/55 R 17 98 V</b>
Tyre size RR:				<b>215/55 R 17 98 V</b>
Tyre type FL:				<b>Winter</b>
Tyre type FR:				<b>Winter</b>
Tyre type RL:				<b>Winter</b>
Tyre type RR:				<b>Winter</b>
Tyre make FL:				<b>258</b>
Tyre make FR:				<b>258</b>
Tyre make RL:				<b>258</b>
Tyre make RR:				<b>258</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		


Instrument panel, complete, Repaired, Acceptable



Seat cover FR, Stain, Cleaning



Bumper F, Scratch(es), Acceptable




Wing FL, Scratch(es), Spot repair



Step L, Dent(s) and scratch(es), Spot repair



Outer sill L, Scratch(es), Acceptable



Door window FL, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Rear light L, Scratch(es), Acceptable



Alloy rim RR, polished, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Acceptable



Step R, Dent(s) and scratch(es), Spot repair



Wing RR, Scratch(es), Polish



Bodywork, No damage, Acceptable

