Print









OPEL Corsa: 2CKZ399

Vinnumber: VXKUPHNSSN4310536 First Registrationdate: 31/08/2022 16038

Expertise Mileage: Bodytype:

Gearbox: Automatic

Transmission: Front Fueltype: Petrol Number of doors 5 Number of seats 5 Number head rests 5

Type of rims (mounted) Aluminium Certificate of Conformity Yes Category Passenger Car Registration Certificate Car (BE) Yes Bodywork

Clean Interior Clean

Corsa 1.2 Turbo S/S Auto GS Line 96kW/131pk 5D/P Auto-8 Versionname:

Fiscalpower: Power Kw:

Body colour Black Type of rims (mounted) Aluminium Parking lot D263

Options

Number of keys total Number keys remote Windows electric F Windows electric R Cruise Control

Steering wheel multifunctional

Seats F heated Airco manual Rims alloy

2 Front parking sensors

2 Rear parking sensors

Limited Technical Inspection

Idle position Sound engine ок ок Engine startingtime Clutch test ок ок Exhaust gass ок Transmission ок

Tyres

	195/55/16/91 V			
Summer tyres:	Fr.L.	Other: 8 mm	Fr.R.	Other: 8 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				

Tyre profile depth FR 8.0 Tyre profile depth RL 6.0 Tyre profile depth RR 6.0 Tyre size FL 195/55 R 16 91 V Tyre size FR 195/55 R 16 91 V Tyre size RL 195/55 R 16 91 H Tyre size RR 195/55 R 16 91 H Tyre type FL All seasons Tyre type FR All Seasons Tyre type RL All seasons Tyre type RR **All Seasons** Tyre make FL 263 Tyre make FR 263 Tyre make RL 259 Tyre make RR 259

Assistance equipment

Repair kit Compressor Yes Yes Number of charging cables (normal) 0

0

Number of charging cables (rapid charge)

Seat cover FR, Stain, Cleaning



Bumper F, Repaired, Acceptable



Door FL, Bad repair, Spot repair







Boot lid covering R, Scratch(es), Acceptable





Rear spoiler, Bad repair, Spot repair









Rear window, Scratch(es), Polish






Wing FR, Bad repair, Spot repair









Roof, Dent(s), Paintless dent repair



