

MACADAM



HYUNDAI Nexo: CDBA388

Vinnnumber:	KMHJ8816FLU009669	Versionname:	Nexo FCEV 1 (Hydrogen) 120kW/163pk 5D/P Auto-1
First Registrationdate:	20/01/2022	Fiscalpower:	
Expertise Mileage:	40999	Power Kw:	
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	N/A
Transmission:	Front	Parking lot:	A202
Fueltype:	Electric		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	N/A		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio	
Number keys remote:	2	Lining leather	
GPS storage:		Sun Roof electric	
GPS storage:	HD	Front parking sensors	
Windows electric F:		Rear parking sensors	
Windows electric R:		Fog lights (front)	
Cruise Control:			
Steering wheel multifunctional:			
Seats F heated:			
Alarm:			
Navigation with screen:			
Airco electronic:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Transmission:	OK
Exhaust gass:	OK		

Tyres

245/45/19/98 W				
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 6 mm	Re.R.	Hankook: 6 mm
Tyre profile depth FL:				5.0
Tyre profile depth FR:				5.0
Tyre profile depth RL:				6.0
Tyre profile depth RR:				6.0
Tyre size FL:				245/45 R 19 98 W
Tyre size FR:				245/45 R 19 98 W
Tyre size RL:				245/45 R 19 98 W
Tyre size RR:				245/45 R 19 98 W
Tyre type FL:				Summer
Tyre type FR:				Summer
Tyre type RL:				Summer
Tyre type RR:				Summer
Tyre make FL:				260
Tyre make FR:				260
Tyre make RL:				260
Tyre make RR:				260

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
-------------	------------	-------------	------------

Number of charging cables (normal)
Number of charging cables (rapid charge)

0
0

Instrument panel, complete, Repaired, Acceptable



Engine insulation, Tear, Replace



Bumper moulding F, Scratch(es), Acceptable



Bonnet, Stone chip(s), Acceptable



Windscreen, Stone chip(s), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Bumper moulding R, Scratch(es), Replace




Step R, Dent(s) and scratch(es), Spot repair



Alloy rim FR polished, Scratch(es), Repair and paint (complete)






Wing RR, Chemical polution, Polish



Alloy rim RR polished, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Bodywork, Inspection +, Photo complémentaire

