


PEUGEOT 2008: 2CMX323

Vinnumber:	VR3UKZKXZNJ712011	Versionname:	2008 e-2008 GT 100kW/136pk 5D/P Auto-1 - WLTP
First Registrationdate:	21/09/2022	Fiscalpower:	incomplet
Expertise Mileage:	30853	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	pp74
Fueltype:	Electric		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		Fog lights (front)
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK


Tyres

215/60/17/96 H				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/60 R 17 96 H
Tyre size FR				215/60 R 17 96 H
Tyre size RL				215/60 R 17 96 H
Tyre size RR				215/60 R 17 96 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Instrument panel, complete, Repaired, Acceptable




Bonnet, Chemical polution, Polish




Door RL, Scratch(es), Polish



Step L, Dent(s) and scratch(es), Spot repair



Wing RL, Scratch(es), Acceptable



Boot moulding, Scratch(es), Acceptable



Bumper R, Scratch(es), Polish



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Wing trim FR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Chemical polution, Polish

