



PEUGEOT 3008: 2BFH857

Vinnnumber:	VF3M45GBUMS223367	Versionname:	3008 Hybrid4 300 e-Auto8 GT Pack (PHEV)
First Registrationdate:	2/11/2021	Fiscalpower:	220kW/299pk 5D/P Auto-8
Expertise Mileage:	85216	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Parking lot:	a119
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol		
Number of seats:	5		
Bodywork:	Clean		
Registration Certificate Car (BE):	Yes		
Number of doors:	5		
Certificate of Conformity:	Yes		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		
Interior:	Clean		

Options

GPS storage	HD	Front parking sensors
Rims alloy		Lining leather
Number of keys total	2	Radio
Windows electric F		Rear parking sensors
Airco electronic		Sun Roof electric
Steering wheel multifunctional		
Seats F heated		
Navigation with screen		
Number keys remote	2	
Windows electric R		
Cruise Control		

Limited Technical Inspection

Engine startingtime	OK	Sound engine	OK
Idle position	OK	Transmission	OK
Exhaust gass	OK	Clutch test	OK

Tyres

	205/55/19/97 V			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre size RR	205/55 R 19 97 V			
Tyre make RR	261			
Tyre profile depth FL	5.0			
Tyre type FR	Summer			
Tyre size FL	205/55 R 19 97 V			
Tyre make FL	265			
Tyre profile depth RL	4.0			
Tyre make RL	261			
Tyre type RR	Summer			
Tyre size RL	205/55 R 19 97 V			
Tyre type FL	Summer			
Tyre type RL	Summer			
Tyre profile depth FR	5.0			
Tyre make FR	265			
Tyre profile depth RR	4.0			
Tyre size FR	205/55 R 19 97 V			

Assistance equipment

Number of charging cables (rapid charge)	1	Compressor	Yes
Repair kit	Yes		

Bonnet, Scratch(es), Polish




Bumper moulding F, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)




Damage Picture - 2




Door FL, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Rear light R, Scratch(es), Polish



Rear light L tailgate, Scratch(es), Polish



Bumper R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Polish



Door RR, Bad repair, Repair and paint (complete)




Wing RR, Scratch(es), Polish



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Step R, Scratch(es), Acceptable



Roof, Chemical polution, Polish





Bodywork, No damage, Acceptable

