



SKODA Enyaq: 2AVQ257

Vinnumber:	TMBJB7NY3NF010029	Versionname:	Enyaq iV 60 132kW/180pk 5D/P Auto-1
First Registrationdate:	5/08/2021	Fiscalpower:	
Expertise Mileage:	99087	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Back	Parking lot	c113
Fueltype:	Electric		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Alarm		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 55 / 19 / 101 / T / Aluminium	4,0 mm	Pirelli	Summer
	Right	235 / 55 / 19 / 101 / T / Aluminium	4,0 mm	Pirelli	Summer
Rear	Left	235 / 55 / 19 / 101 / T / Aluminium	4,0 mm	Pirelli	Summer
	Right	235 / 55 / 19 / 101 / T / Aluminium	4,0 mm	Pirelli	Summer

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	1		

Instrument panel, complete, Repaired, Acceptable



Interior, Stain, Cleaning



Bumper spoiler F, Scratch(es), Replace



Bumper F, Crack, Replace and paint



Headlight L, Crack, Replace




Wing FL, Dent(s), Acceptable



Door FL, Dent(s), Acceptable



Door RL, Scratch(es), Acceptable




Wing RL, Bad repair, Spot repair







Alloy rim RL, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable



Rear light L, Scratch(es), Polish




Bumper R, Scratch(es), Acceptable



Outside rear-view mirror base R, Scratch(es), Smart repair



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Scratch(es), Polish

