


PEUGEOT 208: 2BMX808

Vinnumber:	VR3UHZKXZMT126249	Versionname:	208 e-208 GT Pack 100kW/136pk 5D/P Auto-1
First Registrationdate:	19/01/2022	Fiscalpower:	
Expertise Mileage:	43494	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	D258
Fueltype:	Electric		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio
Number keys remote		
GPS storage	2	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F	HD	Fog lights (front)
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

205/45 R 17 88 V			
Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 5 mm
Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 6 mm

Tyre profile depth FL	4.0
Tyre profile depth FR	5.0
Tyre profile depth RL	5.0
Tyre profile depth RR	6.0
Tyre size FL	205/45 R 17 88 V
Tyre size FR	205/45 R 17 88 V
Tyre size RL	205/45 R 17 88 V
Tyre size RR	205/45 R 17 88 V
Tyre type FL	Winter
Tyre type FR	Winter
Tyre type RL	Winter
Tyre type RR	Winter
Tyre make FL	265
Tyre make FR	265
Tyre make RL	265
Tyre make RR	265

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Number of charging cables (normal)
Number of charging cables (rapid charge)

1
1

Instrument panel, complete, Repaired, Acceptable




Backrest cover RL, Scratch(es), Acceptable



Backrest cover RR, Scratch(es), Acceptable




Seat cover RR, Worn, Acceptable





Windscreen, Stone chip(s), Acceptable




Bumper F, Dent(s) and scratch(es), Spot repair



Bonnet, Chemical polution, Polish




Shutter / cover F, Missing, Replace



Grille, Crack, Replace



Wing FL, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Repair and paint (complete)





Tyre FL, Tear, Acceptable



Door FL, Dent(s), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)




Boot lid covering R, Scratch(es), Acceptable




Tailgate / Boot, Chemical polution, Polish



Rear window, Scratch(es), Polish



Bumper R, Dent(s) and scratch(es), Spot repair



Bumper trim R, Crack, Replace



Alloy rim RR polished, Scratch(es), Repair and paint (complete)




Door RR, Scratch(es), Acceptable



Step R, Scratch(es), Acceptable




Outside rear-view mirror housing R, Scratch(es), Polish



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Door FR, Dent(s), Acceptable



Bodywork, Inspection +, Photo complémentaire



Bodywork, No damage, Acceptable



Bodywork, No damage, Acceptable



Roof, Chemical polution, Polish

