



VOLVO XC60: 2APF357

Vinnnumber:	YV1UZK5VDM1846806	Versionname:	XC60 B4 D Geartronic Momentum Pro 145kW/197pk 5D/P Auto-8
First Registrationdate:	1/06/2021	Fiscalpower:	
Expertise Mileage:	152026	Power Kw:	145
Bodytype:		Body colour	Dark Blue
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Back	Parking lot	b112
Fueltype:	Hybrid Diesel		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Lining leather	
GPS storage		Front parking sensors	
GPS storage	HD	Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Airco functioning	Yes	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Transmission	OK
Exhaust gass	OK		

Tyres

235/60/18/107 V				
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				235/60 R 18 107 V
Tyre size FR				235/60 R 18 107 V
Tyre size RL				235/60 R 18 107 V
Tyre size RR				235/60 R 18 107 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit
Number of charging cables (normal)
Number of charging cables (rapid charge)

Yes
0
0


Compressor

Yes

Instrument panel, complete, Repaired, Acceptable




Windscreen, Stone chip(s), Acceptable




Bonnet, Stone chip(s), Acceptable



Bumper F, Crack, Replace and paint




Bumper moulding F, Scratch(es), Acceptable




Wing FL, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable




Door RL, Scratch(es), Acceptable




Wing RL, Scratch(es), Spot repair









Bumper R, Scratch(es), Acceptable




Boot lid covering R, Scratch(es), Smart repair




Door RR, Dent(s), Acceptable




Outside rear-view mirror housing R, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Roof, Dent(s), Acceptable



Bodywork, No damage, Acceptable

