



### MERCEDES EQS: CDBB462

Vinnnumber:	<b>W1KCG2DBXPA028687</b>	Versionname:	<b>EQS EQS 450+ Luxury Line 245kW/333pk 5D/P Auto-1</b>
First Registrationdate:	<b>6/01/2023</b>	Fiscalpower:	
Expertise Mileage:	<b>77620</b>	Power Kw:	
Bodytype:		Body colour:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Back</b>	Parking lot:	<b>pp94</b>
Fueltype:	<b>Electric</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Bodywork:	<b>Clean</b>		
Interior:	<b>Clean</b>		

### Options

Number of keys total:	<b>2</b>	Radio:	
Number keys remote:	<b>2</b>	Lining leather:	
Windows electric F:		Sun Roof electric:	
Windows electric R:		Front parking sensors:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:			
Seats F heated:			
Alarm:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

### Limited Technical Inspection

Idle position:	<b>OK</b>	Sound engine:	<b>OK</b>
Engine startingtime:	<b>OK</b>	Clutch test:	<b>OK</b>
Exhaust gass:	<b>OK</b>	Transmission:	<b>OK</b>

### Tyres

255/45/20/105 T				
Winter tyres:	Fr.L.	<b>Goodyear: 5 mm</b>	Fr.R.	<b>Goodyear: 5 mm</b>
	Re.L.	<b>Goodyear: 4 mm</b>	Re.R.	<b>Goodyear: 4 mm</b>
Tyre profile depth FL:				<b>5.0</b>
Tyre profile depth FR:				<b>5.0</b>
Tyre profile depth RL:				<b>4.0</b>
Tyre profile depth RR:				<b>4.0</b>
Tyre size FL:				<b>255/45 R 20 105 T</b>
Tyre size FR:				<b>255/45 R 20 105 T</b>
Tyre size RL:				<b>255/45 R 20 105 T</b>
Tyre size RR:				<b>255/45 R 20 105 T</b>
Tyre type FL:				<b>Winter</b>
Tyre type FR:				<b>Winter</b>
Tyre type RL:				<b>Winter</b>
Tyre type RR:				<b>Winter</b>
Tyre make FL:				<b>259</b>
Tyre make FR:				<b>259</b>
Tyre make RL:				<b>259</b>
Tyre make RR:				<b>259</b>

### Assistance equipment

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		


Instrument panel, complete, Repaired, Acceptable



Backrest cover FL, Worn, Acceptable




Bumper F, Scratch(es), Spot repair



Bumper moulding F, Scratch(es), Replace and paint




Bonnet, Stone chip(s), Acceptable




Alloy rim FL polished, Scratch(es), Repair and paint (complete)




Outside rear-view mirror housing L, Scratch(es), Polish



Door FL, Scratch(es), Acceptable



Outer door handle FL, Scratch(es), Acceptable



Wing RL, Dent(s), Spot repair




Alloy rim RL polished, Scratch(es), Acceptable



Charging cable (normal), Missing, Replace



Boot lid covering R, Broken, Smart repair



Bumper R, Scratch(es), Acceptable



Bumper moulding R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Polish



Roof pillar R, Scratch(es), Acceptable



Central pillar R, Scratch(es), Acceptable



Door RR, Dent(s), Paintless dent repair



Wing RR, Scratch(es), Polish



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Bodywork, No damage, Acceptable

