



VOLVO V60: 1XKC867

Vinnumber:	YV1ZW72VDL2376899	Versionname:	V60 D3 Geartronic Momentum 110kW/150pk 5D/P Auto-8
First Registrationdate:	22/01/2020	Fiscalpower:	
Expertise Mileage:	139542	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	pp89
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Lining leather	
Windows electric F		Sun Roof electric	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

225/50/17/98 V				
Winter tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Fulda: 2 mm	Re.R.	Fulda: 2 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				2.0
Tyre profile depth RR				2.0
Tyre size FL				225/50 R 17 98 V
Tyre size FR				225/50 R 17 98 V
Tyre size RL				225/50 R 17 98 V
Tyre size RR				225/50 R 17 98 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				265
Tyre make FR				265
Tyre make RL				2484
Tyre make RR				2484

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	1		

Instrument panel, complete, Repaired, Acceptable




Roof liner, Hole, Smart repair



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Hail damage, Paintless dent repair (hail)




Windscreen, Crack, Replace




Alloy rim FL, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Spot repair



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Mirror side repeater L, Scratch(es), Polish



Roof pillar L, Dent(s), Paintless dent repair




Door FL, Dent(s), Acceptable



Sill trim L, Scratch(es), Spot repair



Door RL, Scratch(es), Acceptable




Wing RL, Dent(s), Spot repair




Alloy rim RL, Scratch(es), Repair and paint (complete)



Side window trim RL, Scratch(es), Acceptable




Internal boot lining R, Scratch(es), Smart repair




Internal boot lining L, Scratch(es), Smart repair



Boot lid covering R, Scratch(es), Smart repair




Rear window, Scratch(es), Polish




Bumper R, Scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Repair and paint (complete)






Wing FR, Dent(s), Acceptable



Door FR, Scratch(es), Polish



Door RR, Scratch(es), Polish




Sill trim R, Scratch(es), Acceptable



Wing RR, Dent(s), Paintless dent repair




Door window RR, Scratch(es), Polish




Alloy rim RR, Scratch(es), Repair and paint (complete)




Panoramic roof, Scratch(es), Polish





Roof, Dent(s) and scratch(es), Repair and paint (complete)



Bodywork, No damage, Acceptable

