



OPEL Grandland: 2CFJ232			
Vinnumber:	W0VZRHNS0N6821776	Versionname:	Grandland 1.2 Turbo S/S AT8 Business Elegance
First Registrationdate:	1/07/2022	Fiscalpower:	96kW/130pk 5D/P Auto-8 - CO2 onvoldedig
Expertise Mileage:	109747	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	a211
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options	
Number of keys total	2
Number keys remote	2
Windows electric F	Radio
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Navigation with screen	
Airco electronic	
Rims alloy	

Limited Technical Inspection			
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres				
Summer tyres:	225/55/18/98 V			
	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL	5.0			
Tyre profile depth FR	5.0			
Tyre profile depth RL	5.0			
Tyre profile depth RR	5.0			
Tyre size FL	225/55 R 18 98 V			
Tyre size FR	225/55 R 18 98 V			
Tyre size RL	225/55 R 18 98 V			
Tyre size RR	225/55 R 18 98 V			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	256			
Tyre make FR	256			
Tyre make RL	256			
Tyre make RR	256			

Assistance equipment			
Spare wheel	Yes	Compressor	Yes
Number of charging cables (normal)	0	Jack	Yes
Number of charging cables (rapid charge)	0		


Instrument panel, complete, Repaired, Acceptable



Bumper moulding F, Scratch(es), Polish



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)




Alloy rim FL polished, Scratch(es), Polish



Outside rear-view mirror base L, Scratch(es), Acceptable




Roof pillar L, Hail damage, Paintless dent repair (hail)



Door FL, Dent(s) and scratch(es), Spot repair







Door RL, Scratch(es), Polish




Step L, Dent(s) and scratch(es), Spot repair



Wing RL, Scratch(es), Spot repair




Wing trim RL, Scratch(es), Acceptable




Alloy rim RL polished, Scratch(es), Polish



Luggage compartment cover, Damaged, Smart repair



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)




Bumper moulding R, Scratch(es), Acceptable




Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Spot repair



Door RR, Dent(s), Paintless dent repair




Wing RR, Dent(s), Acceptable



Alloy rim RR polished, Scratch(es), Polish



Roof pillar R, Hail damage, Paintless dent repair (hail)



Bodywork, No damage, Check



Roof, Hail damage, Repair and paint (complete)

