



## SEAT Ateca: 2DHD183

Vinnumber:	<b>VSSZZZ5F6P6542109</b>	Versionname:	<b>Ateca 1.0 TSI Move Navi 81kW/110pk 5D/P Man-6 (4 seizoenen Banden) - CO2 indicatief</b>
First Registrationdate:	<b>17/03/2023</b>	Fiscalpower:	
Expertise Mileage:	<b>65599</b>	Power Kw:	
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Front</b>	Parking lot:	<b>pp03</b>
Fueltype:	<b>Petrol</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Bodywork:	<b>Clean</b>		
Interior:	<b>Clean</b>		

## Options

Number of keys total	<b>2</b>	Radio
Number keys remote	<b>2</b>	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		Fog lights (front)
Cruise Control		
Steering wheel multifunctional		
Alarm		
Navigation with screen		
Airco electronic		
Rims alloy		

## Limited Technical Inspection

Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Transmission	<b>OK</b>

## Tyres

	<b>215/55/17/98 W</b>			
Winter tyres:	Fr.L.	<b>Vredestein: 2 mm</b>	Fr.R.	<b>Vredestein: 2 mm</b>
	Re.L.	<b>Vredestein: 4 mm</b>	Re.R.	<b>Vredestein: 4 mm</b>
Tyre profile depth FL				<b>2.0</b>
Tyre profile depth FR				<b>2.0</b>
Tyre profile depth RL				<b>4.0</b>
Tyre profile depth RR				<b>4.0</b>
Tyre size FL				<b>215/55 R 17 98 W</b>
Tyre size FR				<b>215/55 R 17 98 W</b>
Tyre size RL				<b>215/55 R 17 98 W</b>
Tyre size RR				<b>215/55 R 17 98 W</b>
Tyre type FL				<b>Winter</b>
Tyre type FR				<b>Winter</b>
Tyre type RL				<b>Winter</b>
Tyre type RR				<b>Winter</b>
Tyre make FL				<b>2480</b>
Tyre make FR				<b>2480</b>
Tyre make RL				<b>2480</b>
Tyre make RR				<b>2480</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Instrument panel, complete, Scratch(es), Acceptable




Seat cover FL, Stain, Cleaning




Bumper moulding F, Scratch(es), Acceptable



Bonnet, Chemical polution, Polish



Wing trim FL, Scratch(es), Replace




Wing FL, Scratch(es), Spot repair




Alloy rim FL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Roof pillar L, Dent(s), Spot repair




Door RL, Dent(s), Paintless dent repair



Wing RL, Scratch(es), Acceptable




Tailgate / Boot, Scratch(es), Polish



Bumper R, Scratch(es), Polish



Door FR, Scratch(es), Acceptable




Door RR, Scratch(es), Acceptable






Wing RR, Scratch(es), Acceptable



Roof pillar R, Dent(s), Acceptable



Roof, Chemical polution, Polish



Bodywork, No damage, Acceptable

