
**OPEL Astra Sports Tourer: 1YNL780**

Vinnnumber:	<b>W0VBD8EV1L8034685</b>	Versionname:	<b>Astra Sports Tourer 1.5 Turbo D S/S Edition</b>
First Registratiodate:	<b>12/10/2020</b>	Fiscalpower:	<b>90kW/122pk 5D/P Man-6</b>
Expertise Mileage:	<b>96443</b>	Power Kw:	
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Front</b>	Parking lot:	<b>d344</b>
Fueltype:	<b>Diesel</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Bodywork:	<b>Clean</b>		
Interior:	<b>Clean</b>		

**Options**

Number of keys total	<b>2</b>	Radio
Number keys remote	<b>2</b>	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		Fog lights (front)
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Navigation with screen		
Airco manual		
Rims alloy		

**Limited Technical Inspection**

Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Transmission	<b>OK</b>

**Tyres**

	<b>205/55/16/91 H</b>			
Winter tyres:	Fr.L.	<b>Firestone: 3 mm</b>	Fr.R.	<b>Firestone: 3 mm</b>
	Re.L.	<b>Firestone: 3 mm</b>	Re.R.	<b>Firestone: 3 mm</b>
Tyre profile depth FL				<b>3.0</b>
Tyre profile depth FR				<b>3.0</b>
Tyre profile depth RL				<b>3.0</b>
Tyre profile depth RR				<b>3.0</b>
Tyre size FL				<b>205/55 R 16 91 H</b>
Tyre size FR				<b>205/55 R 16 91 H</b>
Tyre size RL				<b>205/55 R 16 91 H</b>
Tyre size RR				<b>205/55 R 16 91 H</b>
Tyre type FL				<b>Winter</b>
Tyre type FR				<b>Winter</b>
Tyre type RL				<b>Winter</b>
Tyre type RR				<b>Winter</b>
Tyre make FL				<b>258</b>
Tyre make FR				<b>258</b>
Tyre make RL				<b>258</b>
Tyre make RR				<b>258</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		


Instrument panel, complete, Repaired, Acceptable



Instrument panel, complete, Not functioning (well), Check



Floor covering FL, Burned, Smart repair



Interior, Smell, Ozone treatment



Seat cover FL, Worn, Acceptable



Backrest cover FL, Worn, Acceptable



Roof liner, Hole, Smart repair



Floor covering R, Burned, Smart repair



Seat cover R, Hole, Smart repair



Door panel RL, Scratch(es), Acceptable



Dashboard, Scratch(es), Acceptable



Bumper spoiler F, Deformed / Strained, Replace



Bumper F, Scratch(es), Spot repair



Bumper moulding F, Scratch(es), Replace




Damage Picture - 1

Fog lamp R, Deformed / Strained, Acceptable



Bonnet, Chemical pollution, Polish




Wing FL, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Polish



Door FL, Scratch(es), Spot repair




Door seal FL, Broken, Replace




Central pillar L, Dent(s) and scratch(es), Spot repair



Door RL, Dent(s) and scratch(es), Spot repair




Wing RL, Dent(s), Spot repair





Internal boot lining R, Scratch(es), Smart repair



Internal boot lining L, Scratch(es), Smart repair



Tailgate / Boot, Dent(s), Acceptable



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Damage Picture - 4




Rear light L, Scratch(es), Polish



Boot moulding, Scratch(es), Replace



Door FR, Scratch(es), Spot repair




Door RR, Scratch(es), Polish



Wing RR, Dent(s), Spot repair



Step R, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Chemical pollution, Polish

