



OPEL Corsa: 2CNK245			
Vinnnumber:	VXKUPHNSSN4346487	Versionname:	Corsa 1.2 Turbo S/S Auto GS Line 96kW/131pk
First Registrationdate:	27/09/2022	Fiscalpower:	5D/P Auto-8
Expertise Mileage:	19117	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Parking lot	c409
Transmission:	Front	Type of rims (mounted)	Aluminium
Fueltype:	Petrol		
Number of seats	5		
Bodywork	Clean		
Registration Certificate Car (BE)	Yes		
Number of doors	5		
Certificate of Conformity	Yes		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Category	Passenger Car		
Interior	Clean		

Options			
Airco manual		Front parking sensors	
Rims alloy		Radio	
Number of keys total	2	Rear parking sensors	
Windows electric F			
Steering wheel multifunctional			
Seats F heated			
Number keys remote	2		
Windows electric R			
Cruise Control			

Limited Technical Inspection			
Engine startingtime	OK	Sound engine	OK
Idle position	OK	Transmission	OK
Exhaust gass	OK	Clutch test	OK

Tyres			
195/55/16/91 V			
Summer tyres:	Fr.L.	Other: 7 mm	Fr.R.
	Re.L.	Kleber: 5 mm	Re.R.
Tyre size RR	195/55 R 16 91 H		
Tyre make RR	2479		
Tyre profile depth FL	7.0		
Tyre type FR	All Seasons		
Tyre size FL	195/55 R 16 91 V		
Tyre make FL	263		
Tyre profile depth RL	5.0		
Tyre make RL	2479		
Tyre type RR	All Seasons		
Tyre size RL	195/55 R 16 91 H		
Tyre type FL	All seasons		
Tyre type RL	All seasons		
Tyre profile depth FR	7.0		
Tyre make FR	263		
Tyre profile depth RR	5.0		
Tyre size FR	195/55 R 16 91 V		

Assistance equipment			
Number of charging cables (rapid charge)	0	Compressor	Yes
Repair kit	Yes		
Number of charging cables (normal)	0		

Door panel RR, Scratch(es), Acceptable



Bumper F, Bad repair, Spot repair



Engine, Not functioning (well), Check



Wing RL, Dent(s), Acceptable



Wing FL, Dent(s), Acceptable



Door FR, Dent(s), Paintless dent repair




Roof pillar R, Bad repair, Spot repair




Door RR, Dent(s), Acceptable



Outer sill R, Dent(s), Acceptable



Wing RR, Bad repair, Spot repair



Roof, Dent(s), Paintless dent repair

