



MERCEDES A-Klasse: 1YQN034

Vinnnumber:	W1K1770031V081341	Versionname:	A-Klasse A 180 d Business Solution 85kW/116pk 5D/P Auto-7
First Registrationdate:	5/11/2020	Fiscalpower:	
Expertise Mileage:	53216	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	b506
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Dirty		

Options

Number of keys total:	1	Radio	
Number keys remote:	1	Front parking sensors	
GPS storage:	HD	Rear parking sensors	
Windows electric F:			
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Seats F heated:			
Alarm:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

205/60/16/92 V				
Summer tyres:	Fr.L.	Pirelli: 2 mm	Fr.R.	Pirelli: 2 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm
Tyre profile depth FL:				2.0
Tyre profile depth FR:				2.0
Tyre profile depth RL:				4.0
Tyre profile depth RR:				4.0
Tyre size FL:				205/60 R 16 92 V
Tyre size FR:				205/60 R 16 92 V
Tyre size RL:				205/60 R 16 92 V
Tyre size RR:				205/60 R 16 92 V
Tyre type FL:				Summer
Tyre type FR:				Summer
Tyre type RL:				Summer
Tyre type RR:				Summer
Tyre make FL:				264
Tyre make FR:				264
Tyre make RL:				264
Tyre make RR:				264

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
-------------	------------	-------------	------------

Number of charging cables (normal)
Number of charging cables (rapid charge)

0
0

Ignition key, Missing, Replace




Instrument panel, complete, Repaired, Acceptable



Door panel FL, Scratch(es), Acceptable



Interior, Dirty, Chemical cleaning



Windscreen, Scratch(es), Acceptable



Bonnet, Scratch(es), Polish



Bumper F, Scratch(es), Repair and paint (complete)






Wing RL, Scratch(es), Spot repair




Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Door window RL, Scratch(es), Acceptable




Door window FL, Scratch(es), Polish




Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Polish



Step L, Dent(s) and scratch(es), Spot repair




Rear light R, Scratch(es), Polish




Rear light L, Scratch(es), Polish



Bumper R, Bad repair, Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Acceptable




Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Dent(s), Paintless dent repair



Door RR, Scratch(es), Polish




Step R, Dent(s) and scratch(es), Spot repair




Wing RR, Scratch(es), Polish



Roof pillar R, Bad repair, Spot repair



Roof, Chemical pollution, Polish



Bodywork, No damage, Acceptable

