



VOLVO XC60: 2GDS911

Vinnumber:	YV1UZH4V5S1108777	Versionname:	XC60 T6 PHEV 4x4 Core Aut. (PHEV) 257kW/350pk
First Registrationdate:	7/11/2024	Fiscalpower:	5D/P Auto-8 - CO2 indicatief
Expertise Mileage:	33401	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	4 Wheel-drive	Parking lot:	a323
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio
Number keys remote:	2	Lining leather
GPS storage:	HD	Sun Roof electric
Windows electric F:		Front parking sensors
Windows electric R:		Rear parking sensors
Cruise Control:		
Steering wheel multifunctional:		
Seats F heated:		
Navigation with screen:		
Airco electronic:		
Rims alloy:		

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

Winter tyres:	235/60/18/107 V			
	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL:				5.0
Tyre profile depth FR:				5.0
Tyre profile depth RL:				5.0
Tyre profile depth RR:				5.0
Tyre size FL:				235/60 R 18 107 V
Tyre size FR:				235/60 R 18 107 V
Tyre size RL:				235/60 R 18 107 V
Tyre size RR:				235/60 R 18 107 V
Tyre type FL:				Winter
Tyre type FR:				Winter
Tyre type RL:				Winter
Tyre type RR:				Winter
Tyre make FL:				256
Tyre make FR:				256
Tyre make RL:				256
Tyre make RR:				256

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		

Number of charging cables (rapid charge)

0

Instrument panel, complete, Repaired, Acceptable




Ignition key, Worn, Acceptable



Headlight L, Crack, Replace



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)




Bumper spoiler F, Scratch(es), Replace



Engine insulation, Missing, Check



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Spot repair



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Charging cable (normal), Missing, Replace



Wiper arm rear, Missing, Replace



Rear light L, Scratch(es), Polish



Door RR, Scratch(es), Polish



Roof, Chemical polution, Polish



Bodywork, No damage, Check

