



**MERCEDES A-Klasse: 1WWC475**

Vinnnumber:	<b>WDD1770031J157360</b>	Versionname:	<b>A-Klasse A 180 d Business Solution 85kW/116pk</b>
First Registrationdate:	<b>3/10/2019</b>	Fiscalpower:	<b>5D/P Auto-7</b>
Expertise Mileage:	<b>109990</b>	Power Kw:	
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Front</b>	Parking lot:	<b>b311</b>
Fueltype:	<b>Diesel</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Bodywork:	<b>Clean</b>		
Interior:	<b>Clean</b>		

**Options**

Number of keys total:	<b>2</b>	Radio
Number keys remote:	<b>2</b>	Front parking sensors
Windows electric F:		Rear parking sensors
Windows electric R:		
Cruise Control:		
Steering wheel multifunctional:		
Alarm:		
Navigation with screen:		
Airco electronic:		
Rims alloy:		

**Limited Technical Inspection**

Idle position:	<b>OK</b>	Sound engine:	<b>OK</b>
Engine startingtime:	<b>OK</b>	Clutch test:	<b>OK</b>
Exhaust gass:	<b>OK</b>	Transmission:	<b>OK</b>

**Tyres**

<b>205/60/16/92 V</b>				
Summer tyres:	Fr.L.	<b>Other: 3 mm</b>	Fr.R.	<b>Other: 3 mm</b>
	Re.L.	<b>Continental: 2 mm</b>	Re.R.	<b>Continental: 2 mm</b>
Tyre profile depth FL				<b>3.0</b>
Tyre profile depth FR				<b>3.0</b>
Tyre profile depth RL				<b>2.0</b>
Tyre profile depth RR				<b>2.0</b>
Tyre size FL				<b>205/60 R 16 92 V</b>
Tyre size FR				<b>205/60 R 16 92 V</b>
Tyre size RL				<b>205/60 R 16 92 V</b>
Tyre size RR				<b>205/60 R 16 92 V</b>
Tyre type FL				<b>All seasons</b>
Tyre type FR				<b>All Seasons</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>263</b>
Tyre make FR				<b>263</b>
Tyre make RL				<b>256</b>
Tyre make RR				<b>256</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Instrument panel, complete, Repaired, Acceptable



Centre console, Scratch(es), Acceptable



Door panel FL, Scratch(es), Smart repair




Bumper F, Scratch(es), Spot repair




Bonnet, Dent(s), Acceptable



Windscreen, Stone chip(s), Windscreen repair



Wing FL, Scratch(es), Acceptable



Roof pillar L, Dent(s), Acceptable



Outside rear-view mirror base L, Scratch(es), Smart repair



Central pillar L, Dent(s) and scratch(es), Spot repair



Door FL, Scratch(es), Acceptable



Luggage compartment cover, Damaged, Smart repair



Bumper R, Scratch(es), Spot repair



Alloy rim FR, Scratch(es), Repair and paint (complete)



Mirror side repeater R, Scratch(es), Polish



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Step R, Dent(s), Acceptable



Bodywork, No damage, Acceptable



Roof, Chemical polution, Polish



Fuel cap cover, Deformed / Strained, Replace and paint

