


PEUGEOT 508 SW: 2CSJ155

| | | | |
|------------------------------------|--------------------------|-------------------------|--|
| Vinnnumber: | VR3F4DGZTNY608371 | Versionname: | 508 SW 1.6 Hybrid 225 e-EAT8 Allure Pack (PHEV) |
| First Registrationdate: | 9/11/2022 | Fiscalpower: | 165kW/225pk 5D/P Auto-8 |
| Expertise Mileage: | 72228 | Power Kw: | |
| Bodytype: | | Body colour: | Black |
| Gearbox: | Automatic | Type of rims (mounted): | Aluminium |
| Transmission: | Front | Parking lot: | d045 |
| Fueltype: | Hybrid Petrol | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Type of rims (mounted): | Aluminium | | |
| Certificate of Conformity: | Yes | | |
| Category: | Passenger Car | | |
| Registration Certificate Car (BE): | Yes | | |
| Bodywork: | Clean | | |
| Interior: | Clean | | |

Options

| | | |
|---------------------------------|----------|-----------------------|
| Number of keys total: | 2 | Radio |
| Number keys remote: | 2 | Front parking sensors |
| Windows electric F: | | Rear parking sensors |
| Windows electric R: | | |
| Cruise Control: | | |
| Steering wheel multifunctional: | | |
| Navigation with screen: | | |
| Airco electronic: | | |
| Rims alloy: | | |

Limited Technical Inspection

| | | | |
|----------------------|-----------|---------------|-----------|
| Idle position: | OK | Sound engine: | OK |
| Engine startingtime: | OK | Clutch test: | OK |
| Exhaust gass: | OK | Transmission: | OK |

Tyres

| 215/55/17/98 V | | | | |
|-----------------------|-------|-----------------------|-------|-------------------------|
| Winter tyres: | Fr.L. | Uniroyal: 3 mm | Fr.R. | Uniroyal: 3 mm |
| | Re.L. | Uniroyal: 3 mm | Re.R. | Uniroyal: 3 mm |
| Tyre profile depth FL | | | | 3.0 |
| Tyre profile depth FR | | | | 3.0 |
| Tyre profile depth RL | | | | 3.0 |
| Tyre profile depth RR | | | | 3.0 |
| Tyre size FL | | | | 215/55 R 17 98 V |
| Tyre size FR | | | | 215/55 R 17 98 V |
| Tyre size RL | | | | 215/55 R 17 98 V |
| Tyre size RR | | | | 215/55 R 17 98 V |
| Tyre type FL | | | | Winter |
| Tyre type FR | | | | Winter |
| Tyre type RL | | | | Winter |
| Tyre type RR | | | | Winter |
| Tyre make FL | | | | 265 |
| Tyre make FR | | | | 265 |
| Tyre make RL | | | | 265 |
| Tyre make RR | | | | 265 |

Assistance equipment

| | | | |
|---|------------|-------------|------------|
| Repair kit: | Yes | Compressor: | Yes |
| Number of charging cables (normal): | 1 | | |
| Number of charging cables (rapid charge): | 1 | | |

Instrument panel, complete, Repaired, Acceptable



Interior, Stain, Cleaning



Seat cover FL, Worn, Acceptable



Bonnet, Stone chip(s), Acceptable




Bumper F, Scratch(es), Acceptable




Windscreen, Crack, Replace




Door FL, Scratch(es), Polish



Door RL, Dent(s), Acceptable



Alloy rim FL polished, Scratch(es), Repair and paint (complete)




Wing FL, Scratch(es), Acceptable




Roof pillar L, Scratch(es), Acceptable




Sill trim L, Scratch(es), Polish



Outer door handle FL, Scratch(es), Acceptable



Wing RL, Scratch(es), Polish



Alloy rim RL polished, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Bumper moulding R, Scratch(es), Polish



Rear light L, Scratch(es), Polish



Alloy rim FR polished, Scratch(es), Repair and paint (complete)




Outside rear-view mirror housing R, Scratch(es), Polish



Door RR, Scratch(es), Acceptable



Wing RR, Scratch(es), Acceptable



Step R, Dent(s), Acceptable



Door FR, Scratch(es), Acceptable



Outer door handle FR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Chemical polution, Polish

