



SKODA Kamiq: 2EWA684

Vinnumber:	TMBGP6NW0P3171818	Versionname:	Kamiq 1.0 TSI Clever 70kW/95pk 5D/P Man-5 - CO2 indicatief
First Registrationdate:	15/02/2024	Fiscalpower:	
Expertise Mileage:	24267	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	MAN 5 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	a414
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 55 / 17 / 91 / H / Aluminium	6,0 mm	Vredestein	Winter
	Right	205 / 55 / 17 / 91 / H / Aluminium	6,0 mm	Vredestein	Winter
Rear	Left	205 / 55 / 17 / 91 / H / Aluminium	6,0 mm	Vredestein	Winter
	Right	205 / 55 / 17 / 91 / H / Aluminium	6,0 mm	Vredestein	Winter

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Instrument panel, complete, Repaired, Acceptable




Bumper F, Scratch(es), Spot repair



Bumper moulding F, Scratch(es), Replace



Bonnet, Chemical polution, Polish




Door FL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable




Step L, Scratch(es), Polish



Alloy rim FR, Scratch(es), Polish



Door FR, Dent(s) and scratch(es), Spot repair



Wing RR, Scratch(es), Acceptable



Alloy rim RR, Scratch(es), Polish



Bodywork, No damage, Acceptable



Roof, Chemical polution, Polish

