



MERCEDES A-Klasse Limousine: 2BNH940

Vinnumber:	W1K1771101J345895	Versionname:	Classe A Limousine A 180d Business Solution
First Registrationdate:	24/01/2022	Fiscalpower:	85kW/116pk 4D/P Auto-8
Expertise Mileage:	58462	Power Kw:	85
Bodytype:	Automatic	Body colour:	Black
Gearbox:	Back	Type of rims (mounted):	Aluminium
Transmission:	Back	Parking lot:	A310
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Dirty		

Options

Number of keys total	2	Radio
Number keys remote	2	Front parking sensors
GPS storage		Rear parking sensors
GPS storage	HD	
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Alarm		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

205/60/16/96 H				
Winter tyres:	Fr.L.	Vredestein: 6 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/60 R 16 96 H
Tyre size FR				205/60 R 16 96 H
Tyre size RL				205/60 R 16 96 H
Tyre size RR				205/60 R 16 96 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Number of charging cables (normal)
Number of charging cables (rapid charge)

0
0


Instrument panel, complete, Repaired, Acceptable



Interior, Dirty, Cleaning



Bonnet, Scratch(es), Polish



Windscreen, Stone chip(s), Acceptable



Bumper F, Scratch(es), Spot repair



Door FL, Scratch(es), Acceptable




A-pillar left, Scratch(es), Acceptable




Wing RL, Dent(s), Acceptable



Bumper R, Scratch(es), Spot repair



Wing RR, Dent(s), Acceptable




Alloy rim RR polished, Chemical polution, Acceptable



Door RR, Dent(s), Spot repair



Door RR, Scratch(es), Acceptable



Outer door handle FR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable

