


PEUGEOT 208: 2DBM923

| | | | |
|------------------------------------|--------------------------|-------------------------|--|
| Vinnnummer: | VR3UHZKXZNT677249 | Versionname: | 208 e-208 Active Pack 100kW/136pk 5D/P Auto-1 - WLTP onvolledig |
| First Registrationdate: | 25/01/2023 | Fiscalpower: | |
| Expertise Mileage: | 39582 | Power Kw: | |
| Bodytype: | | Body colour: | Blue |
| Gearbox: | Automatic | Type of rims (mounted): | Steel |
| Transmission: | Front | Parking lot: | d012 |
| Fueltype: | Electric | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Type of rims (mounted): | Steel | | |
| Certificate of Conformity: | Yes | | |
| Category: | Passenger Car | | |
| Registration Certificate Car (BE): | Yes | | |
| Bodywork: | Clean | | |
| Interior: | Clean | | |

Options

| | | | |
|---------------------------------|-----------|-----------------------|--|
| Number of keys total: | 2 | Radio: | |
| Number keys remote: | 2 | Rear parking sensors: | |
| GPS storage: | | | |
| GPS storage: | HD | | |
| Windows electric F: | | | |
| Windows electric R: | | | |
| Cruise Control: | | | |
| Steering wheel multifunctional: | | | |
| Navigation with screen: | | | |
| Airco electronic: | | | |

Limited Technical Inspection

| | | | |
|----------------------|-----------|---------------|-----------|
| Idle position: | OK | Sound engine: | OK |
| Engine startingtime: | OK | Transmission: | OK |
| Exhaust gass: | OK | | |

Tyres

| | | | | |
|------------------------|-----------------------|---------------------|-------|-------------------------|
| | 195/55/16/97 H | | | |
| Winter tyres: | Fr.L. | Fulda: 6 mm | Fr.R. | Fulda: 6 mm |
| | Re.L. | Dunlop: 6 mm | Re.R. | Dunlop: 5 mm |
| Tyre profile depth FL: | | | | 6.0 |
| Tyre profile depth FR: | | | | 6.0 |
| Tyre profile depth RL: | | | | 6.0 |
| Tyre profile depth RR: | | | | 5.0 |
| Tyre size FL: | | | | 195/55 R 16 97 H |
| Tyre size FR: | | | | 195/55 R 16 97 H |
| Tyre size RL: | | | | 195/55 R 16 97 H |
| Tyre size RR: | | | | 195/55 R 16 97 H |
| Tyre type FL: | | | | Winter |
| Tyre type FR: | | | | Winter |
| Tyre type RL: | | | | Winter |
| Tyre type RR: | | | | Winter |
| Tyre make FL: | | | | 2484 |
| Tyre make FR: | | | | 2484 |
| Tyre make RL: | | | | 257 |
| Tyre make RR: | | | | 257 |

Assistance equipment

| | | | |
|---|------------|-------------|------------|
| Repair kit: | Yes | Compressor: | Yes |
| Number of charging cables (normal): | 0 | | |
| Number of charging cables (rapid charge): | 1 | | |

Instrument panel, complete, Repaired, Acceptable



Bumper F, Scratch(es), Spot repair



Headlight L, Scratch(es), Polish



Bonnet, Scratch(es), Acceptable



Wheel cover FL, Crack, Replace



Wing trim FL, Scratch(es), Acceptable



Wing trim RL, Scratch(es), Acceptable



Door FL, Dent(s), Paintless dent repair



Wheel cover RL, Scratch(es), Acceptable



Wing FL, Scratch(es), Polish





Roof pillar L, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Bumper moulding R, Scratch(es), Replace



Boot moulding, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Wheel cover FR, Scratch(es), Replace



Outside rear-view mirror housing R, Scratch(es), Polish



Wing trim RR, Scratch(es), Acceptable



Wheel cover RR, Scratch(es), Replace




Outer sill R, Dent(s), Acceptable



Door FR, Scratch(es), Acceptable



Roof, Scratch(es), Polish



Bodywork, No damage, Acceptable

