


MERCEDES CLA Shooting Brake: 2BAV772

Vinnnumber:	W1K1186101N243739	Versionname:	CLA Shooting Brake CLA 180 d DCT Business
First Registrationdate:	13/09/2021	Fiscalpower:	Solution 85kW/116pk 5D/P Auto-8
Expertise Mileage:	166676	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	b309
Fueltype:	Diesel		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

	205/60/16/92 V			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm
Tyre profile depth FL	3.0			
Tyre profile depth FR	3.0			
Tyre profile depth RL	3.0			
Tyre profile depth RR	3.0			
Tyre size FL	205/60 R 16 92 V			
Tyre size FR	205/60 R 16 92 V			
Tyre size RL	205/60 R 16 92 V			
Tyre size RR	205/60 R 16 92 V			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	256			
Tyre make FR	256			
Tyre make RL	256			
Tyre make RR	256			

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Seat cover R, Stain, Cleaning



Seat cover FR, Stain, Cleaning



Interior covering A pillar R, Scratch(es), Acceptable




Bumper F, Dent(s) and scratch(es), Repair and paint (complete)




Windscreen, Crack, Replace



Door RL, Dent(s) and scratch(es), Spot repair



Wing RL, Dent(s), Acceptable




Outer door handle FL, Scratch(es), Polish




Roof pillar L, Dent(s), Acceptable




Bumper R, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Acceptable




Boot lid covering R, Scratch(es), Smart repair




Rear light L, Scratch(es), Polish




Door FR, Dent(s) and scratch(es), Spot repair




Roof pillar R, Dent(s), Paintless dent repair




Door RR, Dent(s), Paintless dent repair





Wing RR, Scratch(es), Polish




Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Polish



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Bodywork, No damage, Acceptable



Roof, Dent(s), Paintless dent repair

