



PEUGEOT 5008: 2BQD266

Vinnnumber:	VF3MCYHZUMS266529	Versionname:	5008 1.5 BlueHDi S/S EAT8 Roadtrip 96kW/130pk 5D/P Auto-8
First Registrationdate:	11/02/2022	Fiscalpower:	
Expertise Mileage:	103607	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	d045
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Front parking sensors:	
Windows electric F:		Rear parking sensors:	
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

235/55/18/102 V				
Winter tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				235/55 R 18 102 V
Tyre size FR				235/55 R 18 102 V
Tyre size RL				235/55 R 18 102 V
Tyre size RR				235/55 R 18 102 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Instrument panel, complete, Repaired, Acceptable



Seat cover FL, Worn, Acceptable



Windscreen, Stone chip(s), Acceptable



Alloy rim FL polished, Scratch(es), Polish



Door RL, Scratch(es), Acceptable



Step L, Dent(s) and scratch(es), Spot repair



Rear light R, Scratch(es), Polish



Step R, Dent(s) and scratch(es), Spot repair



Wing trim RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Chemical polution, Polish



Engine insulation, Hole, Replace

