



MERCEDES C-Klasse Break: 1XMC077

Vinnnumber:	W1K2052001G001847	Versionname:	C-Klasse Break C 180 d Business Solution
First Registrationdate:	7/02/2020	Fiscalpower:	90kW/122pk 5D/P Auto-9
Expertise Mileage:	101884	Power Kw:	
Bodytype:		Body colour:	Red
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Back	Parking lot:	a401
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

205/60/16/92 H				
Winter tyres:	Fr.L.	Fulda: 4 mm	Fr.R.	Fulda: 4 mm
	Re.L.	Firestone: 4 mm	Re.R.	Firestone: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/60 R 16 92 H
Tyre size FR				205/60 R 16 92 H
Tyre size RL				205/60 R 16 92 H
Tyre size RR				205/60 R 16 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2484
Tyre make FR				2484
Tyre make RL				258
Tyre make RR				258

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		

Instrument panel, complete, Repaired, Acceptable



Seat cover FL, Stain, Cleaning



Steering wheel, Worn, Acceptable



Windscreen, Stone chip(s), Windscreen repair




Wing FL, Scratch(es), Spot repair




Door FL, Scratch(es), Polish



Door window FL, Scratch(es), Polish




Door RL, Dent(s) and scratch(es), Spot repair



Wing RL, Scratch(es), Polish



Bumper R, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Chemical polution, Polish

