




SKODA Karoq: 2BJF821			
Vinnumber:	TMBJP7NU2N5023858	Versionname:	Karoq 1.0 TSI Clever+ 81kW/110pk 5D/P Man-6
First Registrationdate:	6/12/2021	Fiscalpower:	
Expertise Mileage:	39610	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	a311
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options			
Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection			
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres				
Winter tyres:	215/50/18/92 V			
	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/50 R 18 92 V
Tyre size FR				215/50 R 18 92 V
Tyre size RL				215/50 R 18 92 V
Tyre size RR				215/50 R 18 92 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		


Number of charging cables (rapid charge)

0

Instrument panel, complete, Repaired, Acceptable



Interior, Stain, Cleaning



Dashboard, Scratch(es), Acceptable




Glove box, Scratch(es), Acceptable



Bumper spoiler F, Scratch(es), Acceptable




Bonnet, Chemical polution, Polish




Windscreen, Scratch(es), Polish



Door FL, Scratch(es), Spot repair



Door RL, Scratch(es), Polish



Outer door handle RL, Scratch(es), Acceptable




Step L, Scratch(es), Acceptable



Boot lid covering R, Broken, Smart repair



Rear spoiler, Chemical polution, Polish



Bumper R, Scratch(es), Polish




Rear light R, Scratch(es), Polish



Bumper trim R, Scratch(es), Acceptable




Rear window, Scratch(es), Polish



Alloy rim FR polished, Scratch(es), Acceptable



Wing FR, Dent(s), Acceptable



Door FR, Scratch(es), Polish



Door RR, Scratch(es), Polish



Step R, Scratch(es), Acceptable



Wing RR, Scratch(es), Polish



Bodywork, No damage, Acceptable



Roof, Chemical polution, Polish

