



MERCEDES CLA Shooting Brake: 2BRP342

Vinnnumber:	W1K1186861N289799	Versionname:	CLA Shooting Brake CLA 250 e Business Solution (PHEV) 160kW/218pk 5D/P Auto-8
First Registrationdate:	25/02/2022	Fiscalpower:	
Expertise Mileage:	69320	Power Kw:	
Bodytype:		Body colour:	Dark Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	d326
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Lining leather	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

225/45/18/95 V				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/45 R 18 95 V
Tyre size FR				225/45 R 18 95 V
Tyre size RL				225/45 R 18 95 V
Tyre size RR				225/45 R 18 95 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261


Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		

Instrument panel, complete, Repaired, Acceptable



Instrument panel, complete, Not functioning (well), Check




Bumper F, Scratch(es), Spot repair



Wing FL, Scratch(es), Polish



Alloy rim FL polished, Chemical pollution, Polish



Mirror side repeater L, Scratch(es), Polish



Door FL, Scratch(es), Acceptable



Door RL, Scratch(es), Polish



Outer door handle RL, Scratch(es), Acceptable



Alloy rim RL polished, Chemical pollution, Polish



Bumper R, Scratch(es), Acceptable



Alloy rim FR polished, Chemical polution, Polish



Wing FR, Scratch(es), Acceptable



Door FR, Repaired, Acceptable



Mirror side repeater R, Scratch(es), Polish



Door RR, Repaired, Acceptable



Alloy rim RR polished, Chemical polution, Polish



Bodywork, No damage, Acceptable

