



PEUGEOT 2008: 2CNP579

Vinnumber:	VR3USHNSKNJ720918	Versionname:	2008 1.2 Puretech S/S Active Pack 96kW/130pk 5D/P Man-6
First Registrationdate:	28/09/2022	Fiscalpower:	
Expertise Mileage:	94622	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	b304
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	1	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Summer tyres:	215/65/16/98 H			
	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm
Tyre profile depth FL	3.0			
Tyre profile depth FR	3.0			
Tyre profile depth RL	3.0			
Tyre profile depth RR	3.0			
Tyre size FL	215/65 R 16 98 H			
Tyre size FR	215/65 R 16 98 H			
Tyre size RL	215/65 R 16 98 H			
Tyre size RR	215/65 R 16 98 H			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	256			
Tyre make FR	256			
Tyre make RL	256			
Tyre make RR	256			

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Instrument panel, complete, Repaired, Acceptable



Seat cover R, Stain, Cleaning




Roof liner, Hole, Smart repair



Engine insulation, Damaged, Replace



Bonnet, Scratch(es), Polish



Wing FL, Scratch(es), Acceptable



Wing trim FL, Scratch(es), Replace



Door FL, Dent(s), Paintless dent repair



Central pillar L, Dent(s) and scratch(es), Spot repair



Door RL, Dent(s), Paintless dent repair



Roof pillar L, Chemical polution, Polish



Rear light L, Scratch(es), Polish



Bumper R, Scratch(es), Spot repair



Bumper trim R, Scratch(es), Smart repair



Rear light R tailgate, Scratch(es), Polish



Door RR, Repaired, Acceptable



Bodywork, Not original part, Remove lettering



Bodywork, No damage, Acceptable

