



OPEL Corsa: 2CQH834

Vinnnumber:	VXKUPHNSSN4381231	Versionname:	Corsa 1.2 Turbo S/S Auto GS Line 96kW/131pk
First Registrationdate:	18/10/2022	Fiscalpower:	5D/P Auto-8
Expertise Mileage:	29638	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	Bocht 103
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Front parking sensors
Number keys remote	2	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Airco manual		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

195/55/16/91 V				
Summer tyres:	Fr.L.	Other: 7 mm	Fr.R.	Other: 7 mm
	Re.L.	Other: 7 mm	Re.R.	Other: 7 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				195/55 R 16 91 V
Tyre size FR				195/55 R 16 91 V
Tyre size RL				195/55 R 16 91 V
Tyre size RR				195/55 R 16 91 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				263
Tyre make FR				263
Tyre make RL				263
Tyre make RR				263

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Seat cover R, Stain, Cleaning



Bumper F, Not original part, Acceptable



Bonnet, Dent(s) and scratch(es), Spot repair




Mirror side repeater L, Scratch(es), Polish




Boot lid covering R, Scratch(es), Acceptable



Bumper R, Bad repair, Spot repair



Door FR, Bad repair, Spot repair



Roof, Repaired, Acceptable

