

MACADAM



MERCEDES EQS: CDBB461

Vinnnumber:	W1KCG2DBXPA028768	Versionname:	EQS EQS 450+ Luxury Line 245kW/333pk 5D/P Auto-1
First Registrationdate:	6/01/2023	Fiscalpower:	
Expertise Mileage:	69033	Power Kw:	
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Back	Parking lot:	pp49
Fueltype:	Electric		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Lining leather:	
GPS storage:	HD	Sun Roof electric:	
Windows electric F:		Front parking sensors:	
Windows electric R:		Rear parking sensors:	
Cruise Control:			
Steering wheel multifunctional:			
Seats F heated:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

255/45/20/105 T				
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 2 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				2.0
Tyre size FL				255/45 R 20 105 T
Tyre size FR				255/45 R 20 105 T
Tyre size RL				255/45 R 20 105 T
Tyre size RR				255/45 R 20 105 T
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		


Instrument panel, complete, Repaired, Acceptable



Bonnet, Repaired, Acceptable



Bumper F, Scratch(es), Spot repair



Grille, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Polish





Door RL, Scratch(es), Polish





Door FL, Scratch(es), Acceptable



Wing FL, Scratch(es), Polish



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Charging cable (normal), Missing, Check



Rear spoiler, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Polish



Rear light R, Scratch(es), Polish



Rear light R tailgate, Scratch(es), Polish




Rear light L, Scratch(es), Polish




Bumper R, Scratch(es), Polish



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Polish



Door RR, Scratch(es), Polish





Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Polish

