



OPEL Grandland: 2DAW660

Vinnnumber:	W0VZCYHZ0N6842914	Versionname:	Grandland 1.5 Turbo D S/S AT8 Business Elegance
First Registrationdate:	18/01/2023	Fiscalpower:	96kW/130pk 5D/P Auto-8
Expertise Mileage:	188610	Power Kw:	
Bodytype:	Automatic	Body colour	Black
Gearbox:	Front	Type of rims (mounted)	Aluminium
Transmission:	Diesel	Parking lot	c414
Fueltype:			
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Lining leather	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Fog lights (front)	
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 55 / 18 / 102 / V / Aluminium	5,0 mm	Michelin	Winter
	Right	225 / 55 / 18 / 102 / V / Aluminium	4,0 mm	Michelin	Summer
Rear	Left	225 / 55 / 18 / 102 / V / Aluminium	5,0 mm	Michelin	Summer
	Right	225 / 55 / 18 / 102 / V / Aluminium	4,0 mm	Michelin	Summer


Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Instrument panel, complete, Repaired, Acceptable



Seat cover FL, Hole, Smart repair



Backrest cover FL, Worn, Acceptable




Steering wheel, Worn, Acceptable



Bumper spoiler F, Scratch(es), Acceptable



Door FL, Scratch(es), Polish



Door RL, Scratch(es), Acceptable



Step L, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Luggage compartment cover, Damaged, Smart repair



Boot lid covering R, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Rear wiper blade, Incomplete, Replace




Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Acceptable



Door RR, Scratch(es), Polish



Bodywork, No damage, Acceptable

