



PEUGEOT 308 SW: 2CGL452

Vinnnumber:	VR3FRHNSLNY572067	Versionname:	308 SW 1.2 PureTech 130 S/S Allure Pack
First Registrationdate:	14/07/2022	Fiscalpower:	96kW/130pk 5D/P Man-6
Expertise Mileage:	29787	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	c309
Fueltype:	Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio	
Number keys remote:	2	Front parking sensors	
Windows electric F:		Rear parking sensors	
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 45 / 17 / 94 / V / Aluminium	4,0 mm	Michelin	Summer
	Right	225 / 45 / 17 / 94 / V / Aluminium	4,0 mm	Michelin	Summer
Rear	Left	225 / 45 / 17 / 94 / V / Aluminium	4,0 mm	Michelin	Summer
	Right	225 / 45 / 17 / 94 / V / Aluminium	4,0 mm	Michelin	Summer

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Instrument panel, complete, Repaired, Acceptable



Bumper grille, Broken, Replace



Bumper F, Scratch(es), Repair and paint (complete)



Grille, Broken, Replace



Alloy rim FL polished, Scratch(es), Repair and paint (complete)




Step L, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)




Bumper moulding R, Scratch(es), Polish



Alloy rim FR polished, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Engine insulation, Hole, Replace

