



HYUNDAI Santa Fe: 2ARC277

Vinnnumber:	KMHS6812DMU009345	Versionname:	Santa Fe 1.6 T-GDi Plug-in Hybrid 4x4 Shine Aut. (PHEV) 195kW/265pk 5D/P Auto-6
First Registrationdate:	17/06/2021	Fiscalpower:	
Expertise Mileage:	142818	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	4 Wheel-drive	Parking lot:	b202
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Lining leather
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 45 / 19 / 105 / V / Aluminium	4,0 mm	Cooper	Summer
	Right	235 / 45 / 19 / 105 / V / Aluminium	4,0 mm	Cooper	Summer
Rear	Left	235 / 45 / 19 / 105 / V / Aluminium	3,0 mm	Continental	Summer
	Right	235 / 45 / 19 / 105 / V / Aluminium	3,0 mm	Continental	Summer

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	0		


Instrument panel, complete, Repaired, Acceptable



Steering wheel, Worn, Acceptable




Bonnet, Repaired, Acceptable



Door RL, Scratch(es), Acceptable




Step L, Dent(s) and scratch(es), Spot repair



Alloy rim RL polished, Chemical polution, Polish




Internal boot lining L, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Smart repair




Boot lid covering R, Scratch(es), Smart repair



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s), Acceptable



Outside rear-view mirror base R, Scratch(es), Polish



Door RR, Dent(s) and scratch(es), Spot repair



Alloy rim RR polished, Scratch(es), Polish



Wing FR, Scratch(es), Polish



Bodywork, No damage, Acceptable



Roof, Dent(s), Acceptable

