



SKODA Kamiq: 2BPB615

Vinnnumber:	TMBGH6NW7N3059608	Versionname:	Kamiq 1.0 TGI Clever 66kW/90pk 5D/P Man-6
First Registrationdate:	1/02/2022	Fiscalpower:	
Expertise Mileage:	34254	Power Kw:	
Bodytype:		Body colour:	Dark Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	a402
Fueltype:	Gas		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Front parking sensors:	
Windows electric F:		Rear parking sensors:	
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Seats F heated:			
Alarm:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

205/55/17/95 V				
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 17 95 V
Tyre size FR				205/55 R 17 95 V
Tyre size RL				205/55 R 17 95 V
Tyre size RR				205/55 R 17 95 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259


Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		

Instrument panel, complete, Repaired, Acceptable



Bonnet, Chemical polution, Polish



Wing FL, Bad repair, Check




Door FL, Bad repair, Check



Wing RL, Bad repair, Repair and paint (complete)




Door RL, Bad repair, Repair and paint (complete)




Outer door handle FL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Smart repair



Wing RR, Dent(s) and scratch(es), Acceptable




Door FR, Dent(s), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Outer door handle FR, Scratch(es), Acceptable



Outer door handle RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Chemical pollution, Polish

