



PEUGEOT 2008: 2BLX040

Vinnumber:	VR3USHNSKMJ914225	Versionname:	2008 1.2 Puretech S/S Active Pack 96kW/130pk 5D/P Man-6
First Registrationdate:	7/01/2022	Fiscalpower:	
Expertise Mileage:	84715	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	D029
Fueltype:	Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio:	
Number keys remote:	1	Front parking sensors:	
GPS storage:		Rear parking sensors:	
GPS storage:	HD		
Windows electric F:			
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Seats F heated:			
Alarm:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

215/65/16/98 H				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				4.0
Tyre profile depth RR				5.0
Tyre size FL				215/65 R 16 98 H
Tyre size FR				215/65 R 16 98 H
Tyre size RL				215/65 R 16 98 H
Tyre size RR				215/65 R 16 98 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit
Number of charging cables (normal)
Number of charging cables (rapid charge)

Yes
0
0

Compressor

Yes

Instrument panel, complete, Repaired, Acceptable



Interior covering A pillar L, Scratch(es), Acceptable



Bonnet, Stone chip(s), Acceptable




Engine insulation, Missing, Check



Alloy rim RL, Scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Spot repair



Door FL, Scratch(es), Acceptable



Tailgate / Boot, Dent(s), Acceptable



Bumper R, Scratch(es), Acceptable



Bumper moulding R, Scratch(es), Acceptable



Door FR, Dent(s) and scratch(es), Spot repair



Alloy rim FR, Scratch(es), Polish



Alloy rim RR, Scratch(es), Acceptable



Roof, Hail damage, Paintless dent repair (hail)



Bodywork, No damage, Acceptable



Bodywork, Dirty, Cleaning

