

MERCEDES A-Klasse Limousine: 2BQY985

Vinnnumber:	W1K1771861J350643	Versionname:	A-Klasse Limousine A 250e Business Solution (PHEV) 160kW/218pk 4D/P Auto-8
First Registrationdate:	21/02/2022	Fiscalpower:	
Expertise Mileage:	73096	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	b522
Fueltype:	Hybrid Petrol		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

205/55/16/95 V				
Winter tyres:	Fr.L.	BF Goodrich: 4 mm	Fr.R.	BF Goodrich: 4 mm
	Re.L.	BF Goodrich: 4 mm	Re.R.	BF Goodrich: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 16 95 V
Tyre size FR				205/55 R 16 95 V
Tyre size RL				205/55 R 16 95 V
Tyre size RR				205/55 R 16 95 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2485
Tyre make FR				2485
Tyre make RL				2485
Tyre make RR				2485

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		

Instrument panel, complete, Repaired, Acceptable



Steering wheel, Worn, Acceptable



Bumper F, Scratch(es), Spot repair



Bonnet, Chemical polution, Polish



Door FL, Chemical polution, Polish



Alloy rim RL polished, Scratch(es), Acceptable



Tailgate / Boot, Chemical polution, Polish



Bumper trim R, Scratch(es), Acceptable




Alloy rim FR polished, Scratch(es), Acceptable




Mirror side repeater R, Scratch(es), Polish



Outside rear-view mirror housing R, Scratch(es), Polish



Door FR, Dent(s) and scratch(es), Spot repair



Outer door handle FR, Scratch(es), Acceptable



Bodywork, No damage, Check



Roof, Repaired, Acceptable

