


PEUGEOT 2008: 2BTX448

Vinnnummer:	VR3USHNSSNJ575720	Versionname:	2008 1.2 Puretech S/S EAT8 GT Pack 96kW/130pk 5D/P Auto-8
First Registrationdate:	22/03/2022	Fiscalpower:	
Expertise Mileage:	105493	Power Kw:	96
Bodytype:		Body colour:	Dark Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	c326
Fueltype:	Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio
Number keys remote:	2	Front parking sensors
Windows electric F:		Rear parking sensors
Windows electric R:		
Cruise Control:		
Steering wheel multifunctional:		
Seats F heated:		
Navigation with screen:		
Airco electronic:		
Rims alloy:		

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

215/55/18/99 V				
Summer tyres:	Fr.L.	Vredestein: 1 mm	Fr.R.	Vredestein: 1 mm
	Re.L.	Vredestein: 2 mm	Re.R.	Vredestein: 2 mm
Tyre profile depth FL:				1.0
Tyre profile depth FR:				1.0
Tyre profile depth RL:				2.0
Tyre profile depth RR:				2.0
Tyre size FL:				215/55 R 18 99 V
Tyre size FR:				215/55 R 18 99 V
Tyre size RL:				215/55 R 18 99 V
Tyre size RR:				215/55 R 18 99 V
Tyre type FL:				All seasons
Tyre type FR:				All Seasons
Tyre type RL:				All seasons
Tyre type RR:				All Seasons
Tyre make FL:				2480
Tyre make FR:				2480
Tyre make RL:				2480
Tyre make RR:				2480

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Instrument panel, complete, Repaired, Acceptable



Instrument panel, complete, Not functioning (well), Check



Engine insulation, Damaged, Replace




Bonnet, Chemical pollution, Polish



Headlight L, Scratch(es), Polish




Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Wheel cover FL, Scratch(es), Replace



Door FL, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable




Door RL, Scratch(es), Polish





Step L, Scratch(es), Acceptable




Boot lid covering R, Scratch(es), Acceptable



Bumper moulding R, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Acceptable



Luggage compartment cover, Damaged, Acceptable



Tailgate / Boot, Scratch(es), Polish



Rear window, Scratch(es), Polish



Wing trim RR, Scratch(es), Acceptable




Door RR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Tyre FR, Worn, Acceptable



Roof, Chemical pollution, Polish



Bodywork, No damage, Acceptable

