Print









OPEL Corsa: 2CSQ348

Vinnumber: VXKUPHNSSN4399415 First Registrationdate:

14/11/2022 Expertise Mileage: 16041

Bodytype:

Number of seats

Gearbox: Automatic Transmission: Front Fueltype: Petrol Number of doors 5

5 Number head rests 5 Type of rims (mounted) Aluminium Certificate of Conformity Yes

Category Passenger Car Registration Certificate Car (BE) Yes Bodywork Clean

Interior Clean

Corsa 1.2 Turbo S/S Auto GS Line 96kW/131pk 5D/P Auto-8 Versionname:

Fiscalpower: Power Kw:

Body colour Black Type of rims (mounted) Aluminium Parking lot bocht 22

259

## Options

Number of keys total Number keys remote Windows electric F Windows electric R

Cruise Control Steering wheel multifunctional

Seats F heated Airco manual Rims alloy

2 Radio

Front parking sensors Rear parking sensors

#### **Limited Technical Inspection**

Idle position Sound engine ок ок Engine startingtime Clutch test ок ок Exhaust gass ок Transmission ок

### Tyres

	195/55/16/91 V			
Summer tyres:	Fr.L.	Other: 7 mm	Fr.R.	Other: 7 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FI				

Tyre profile depth FR 7.0 Tyre profile depth RL 6.0 Tyre profile depth RR 6.0 Tyre size FL 195/55 R 16 91 V Tyre size FR 195/55 R 16 91 V Tyre size RL 195/55 R 16 91 H Tyre size RR 195/55 R 16 91 H Tyre type FL All seasons Tyre type FR All Seasons Tyre type RL All seasons Tyre type RR **All Seasons** Tyre make FL 263 Tyre make FR 263 Tyre make RL 259 Tyre make RR

#### Assistance equipment


Compressor Yes Yes Number of charging cables (normal) 0

0

Number of charging cables (rapid charge)

# Boot lid covering R, Scratch(es), Acceptable





Bumper R, Scratch(es), Acceptable





Wing RR, Bad repair, Spot repair





Roof pillar R, Bad repair, Spot repair









Central pillar R, Bad repair, Spot repair





Roof, Dent(s), Acceptable





