



HYUNDAI Tucson: 2BPB616			
Vinnumber:	TMAJD812DNJ077229	Versionname:	Tucson 1.6 T-GDi Plug-in Hybrid 4x4 Feel (PHEV)
First Registrationdate:	1/02/2022	Fiscalpower:	195kW/265pk 5D/P Auto-6
Expertise Mileage:	70053	Power Kw:	132
Bodytype:	Automatic	Body colour	Blue
Gearbox:	Front	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	d268
Fueltype:	Hybrid Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options	
Number of keys total	2
Number keys remote	2
Windows electric F	Radio
Windows electric R	Lining leather
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	Fog lights (front)
Navigation with screen	
Airco electronic	
Rims alloy	

Limited Technical Inspection			
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres					
Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 50 / 19 / 103 / V / Aluminium	4,0 mm	Vredestein	All season
	Right	235 / 50 / 19 / 103 / V / Aluminium	4,0 mm	Vredestein	All season
Rear	Left	235 / 50 / 19 / 103 / V / Aluminium	4,0 mm	Continental	All season
	Right	235 / 50 / 19 / 103 / V / Aluminium	4,0 mm	Continental	All season

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Instrument panel, complete, Not functioning (well), Check




Instrument panel, complete, Repaired, Acceptable
--



Bumper F, Scratch(es), Polish




Bonnet, Repaired, Acceptable



Wing FL, Scratch(es), Polish



Step L, Dent(s) and scratch(es), Spot repair




Central pillar L, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)




Door RL, Dent(s), Acceptable




Wing RL, Scratch(es), Acceptable




Boot lid covering R, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Acceptable




Rear spoiler, Scratch(es), Polish




Bumper R, Scratch(es), Acceptable



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door trim RR, Scratch(es), Replace



Wing trim RR, Scratch(es), Replace



Alloy rim FR polished, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Wing RR, Scratch(es), Spot repair



Bodywork, No damage, Acceptable

