



SKODA Superb Combi: 2BSJ997

Vinnnumber:	TMBJH9NP9N7032631	Versionname:	Superb Combi 2.0 CRTDI DSG7 Clever
First Registrationdate:	7/03/2022	Fiscalpower:	110kW/150pk 5D/P Auto-7
Expertise Mileage:	160357	Power Kw:	
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	pp02
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Front parking sensors:	
Windows electric F:		Rear parking sensors:	
Windows electric R:		Fog lights (front):	
Cruise Control:			
Steering wheel multifunctional:			
Seats F heated:			
Alarm:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK


Tyres

215/60/16/95 H				
Winter tyres:	Fr.L.	Dunlop: 3 mm	Fr.R.	Dunlop: 3 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/60 R 16 95 H
Tyre size FR				215/60 R 16 95 H
Tyre size RL				215/60 R 16 95 H
Tyre size RR				215/60 R 16 95 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				257
Tyre make FR				257
Tyre make RL				257
Tyre make RR				257

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		

Floor covering FL, Worn, Acceptable



Instrument panel, complete, Repaired, Acceptable



Engine insulation, Tear, Replace



Windscreen, Stone chip(s), Windscreen repair




Bumper F, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Polish



Wing RL, Scratch(es), Polish




Bumper R, Scratch(es), Repair and paint (complete)






Bumper trim R, Scratch(es), Acceptable




Alloy rim FR, Scratch(es), Repair and paint (complete)



Door FR, Dent(s), Acceptable



Door RR, Scratch(es), Polish



Wing RR, Dent(s), Spot repair



Bodywork, No damage, Acceptable



Roof, Dent(s) and scratch(es), Repair and paint (complete)

