



SKODA Scala: 2BRT007			
Vinnnumber:	TMBEK6NW5N3064797	Versionname:	Scala 1.5 DSG7 Clever+ 110kW/150pk 5D/P Auto-7
First Registrationdate:	28/02/2022	Fiscalpower:	
Expertise Mileage:	39076	Power Kw:	
Bodytype:		Body colour	Blue
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	c317
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options			
Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
GPS storage		Rear parking sensors	
GPS storage	HD	Fog lights (front)	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection			
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Transmission	OK
Exhaust gass	OK		

Tyres				
Winter tyres:	205/45/18/90 H			
	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/45 R 18 90 H
Tyre size FR				205/45 R 18 90 H
Tyre size RL				205/45 R 18 90 H
Tyre size RR				205/45 R 18 90 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment			
Spare wheel	Yes	Jack	Yes

Number of charging cables (normal)
Number of charging cables (rapid charge)

0
0

Instrument panel, complete, Repaired, Acceptable



Bumper F, Scratch(es), Spot repair




Alloy rim RR, Scratch(es), Repair and paint (complete)



Door FR, Dent(s), Paintless dent repair



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Tyre FR, Tear, Replace



Alloy rim FR, Scratch(es), Repair and paint (complete)



Bodywork, No damage, Acceptable

