



SKODA Octavia Combi: 2EBE343

Vinnumber:	TMBJG8NX1RY009227	Versionname:	Octavia Combi 2.0 CRTDI DSG7 Clever 85kW/115pk
First Registrationdate:	14/08/2023	Fiscalpower:	5D/P Auto-7 - CO2 indicatief
Expertise Mileage:	67096	Power Kw:	
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	c408
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	3	Radio	
Number keys remote:	3	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Fog lights (front)	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK


Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 60 / 16 / 92 / V / Aluminium	4,0 mm	Kumho	Summer
	Right	205 / 60 / 16 / 92 / V / Aluminium	4,0 mm	Kumho	Summer
Rear	Left	205 / 60 / 16 / 92 / V / Aluminium	4,0 mm	Kumho	Summer
	Right	205 / 60 / 16 / 92 / V / Aluminium	4,0 mm	Kumho	Summer


Assistance equipment

Spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		


Instrument panel, complete, Repaired, Acceptable



Wing FL, Dent(s), Acceptable




Alloy rim FL, Scratch(es), Repair and paint (complete)



Door FL, Dent(s), Acceptable




Boot lid covering R, Scratch(es), Smart repair



Tailgate / Boot, Bad repair, Repair and paint (complete)




Bumper R, Scratch(es), Spot repair



Wing FR, Scratch(es), Acceptable




Door FR, Dent(s), Acceptable



Door RR, Repaired, Acceptable



Wing RR, Bad repair, Repair and paint (complete)



Bodywork, No damage, Acceptable

