



MERCEDES A-Klasse Limousine: 2BET016			
Vinnumber:	W1K1771861J333091	Versionname:	A-Klasse Limousine A 250e Business Solution (PHEV) 160kW/218pk 4D/P Auto-8
First Registrationdate:	25/10/2021	Fiscalpower:	
Expertise Mileage:	74520	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	c122
Fueltype:	Hybrid Petrol		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options	
Number of keys total	2
Number keys remote	2
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Alarm	
Navigation with screen	
Airco electronic	
Rims alloy	

Limited Technical Inspection			
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres			
205/55/17/95 V			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.
	Re.L.	Continental: 3 mm	Re.R.
Tyre profile depth FL			3.0
Tyre profile depth FR			3.0
Tyre profile depth RL			3.0
Tyre profile depth RR			3.0
Tyre size FL			205/55 R 17 95 V
Tyre size FR			205/55 R 17 95 V
Tyre size RL			205/55 R 17 95 V
Tyre size RR			205/55 R 17 95 V
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			256
Tyre make RL			256
Tyre make RR			256

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		

Centre console, Scratch(es), Acceptable



Bumper F, Scratch(es), Acceptable




Windscreen, Stone chip(s), Windscreen repair



Wing FL, Scratch(es), Acceptable




Door RL, Dent(s), Acceptable



Door FL, Scratch(es), Acceptable



Central pillar L, Dent(s) and scratch(es), Spot repair



Step L, Scratch(es), Acceptable




Wing RL, Scratch(es), Polish




Alloy rim RL polished, Scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Polish



Alloy rim FR polished, Scratch(es), Acceptable




Door RR, Dent(s) and scratch(es), Spot repair




Central pillar R, Dent(s), Acceptable



Step R, Dent(s) and scratch(es), Spot repair




Wing RR, Dent(s), Spot repair



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Roof pillar R, Dent(s), Paintless dent repair



Roof, Chemical polution, Polish



Bodywork, No damage, Check

