



PEUGEOT 508 SW: 2BHA555

Vinnnumber:	VR3F4DGZTMY538513	Versionname:	508 SW 1.6 Hybrid 225 e-EAT8 GT (PHEV)
First Registrationdate:	23/11/2021	Fiscalpower:	165kW/225pk 5D/P Auto-8
Expertise Mileage:	53833	Power Kw:	
Bodytype:		Body colour	Dark Blue
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	c321
Fueltype:	Hybrid Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

235/45/17/98 Y				
Summer tyres:	Fr.L.	Vredestein: 3 mm	Fr.R.	Vredestein: 3 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				235/45 R 17 98 Y
Tyre size FR				235/45 R 17 98 Y
Tyre size RL				235/45 R 17 98 Y
Tyre size RR				235/45 R 17 98 Y
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Instrument panel, complete, Not functioning (well), Acceptable



Bumper F, Scratch(es), Acceptable



Bonnet, Scratch(es), Polish



Alloy rim FL polished, Scratch(es), Acceptable



Door RL, Dent(s), Paintless dent repair



Door FL, Scratch(es), Acceptable




Boot carpet, Scratch(es), Acceptable



Bumper R, Scratch(es), Polish





Alloy rim RR polished, Scratch(es), Acceptable




Alloy rim FR polished, Scratch(es), Acceptable



Door FR, Dent(s), Paintless dent repair




Door RR, Dent(s) and scratch(es), Spot repair



Damage Picture - 4


Wing RR, Dent(s), Acceptable



Roof pillar R, Scratch(es), Polish



Outer sill R, Dent(s), Paintless dent repair



Bodywork, No damage, Acceptable



Roof, Dent(s), Acceptable

