



PEUGEOT 508: 2BCX334

Vinnumber:	VR3F3DGZTMY529700	Versionname:	508 1.6 Hybrid 225 e-EAT8 GT (PHEV)
First Registrationdate:	5/10/2021	Fiscalpower:	
Expertise Mileage:	100682	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:		Type of rims (mounted)	Aluminium
Transmission:	Automatic	Parking lot	b407
Fueltype:	Front		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Hybrid Petrol		
Certificate of Conformity	Aluminium		
Category	Yes		
Registration Certificate Car (BE)	Passenger Car		
Bodywork	Yes		
Interior	Clean		
Clean			

Options

Number of keys total	2	Radio
Number keys remote	2	Front parking sensors
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

235/45/18/98 Y			
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.
	Re.L.	Vredestein: 5 mm	Re.R.
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			235/45 R 18 98 Y
Tyre size FR			235/45 R 18 98 Y
Tyre size RL			235/45 R 18 98 Y
Tyre size RR			235/45 R 18 98 Y
Tyre type FL			All seasons
Tyre type FR			All Seasons
Tyre type RL			All seasons
Tyre type RR			All Seasons
Tyre make FL			2480
Tyre make FR			2480
Tyre make RL			2480
Tyre make RR			2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		


Instrument panel, complete, Not functioning (well), Acceptable



Bonnet, Scratch(es), Polish




Bumper F, Scratch(es), Spot repair




Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Spot repair




Wing RL, Scratch(es), Polish



Door FL, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Polish



Wing FL, Scratch(es), Polish



Bumper R, Scratch(es), Repair and paint (complete)



Supplementary brake light, Scratch(es), Replace



Rear light L, Scratch(es), Polish




Rear light R, Scratch(es), Polish



Wing FR, Scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)




Outside rear-view mirror housing R, Scratch(es), Acceptable




Door FR, Scratch(es), Polish



Door RR, Scratch(es), Polish



Wing RR, Dent(s), Spot repair



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Bodywork, No damage, Acceptable

